

| Supervision | 2000 % | 2004 % | 2000 Grade | 2004 Grade |
|--|-------------------|-------------------|-----------------------|-----------------------|
| Adults present | 100 | 100 | A+ | A+ |
| Easily viewed | 100 | 96 | A+ | A |
| Crawl spaces | 98 | 68 | A | D+ |
| Supervision rules posted | 2 | 0 | F | F |
| Overall Grade: Supervision | | | B+ | B- |
| | | | | |
| Age-Appropriate Design | 2000 % | 2004 % | 2000 Grade | 2004 Grade |
| Had separate areas | 9 | 67 | F | D+ |
| Signage for age group provided | NA | 0 | NA | F |
| Provided change of direction | 98 | 93 | A | A- |
| Had guardrails | 96 | 90 | A | A- |
| Prevented climbing outside the structure | 93 | 91 | A- | A- |
| Supporting structure prevented climbing on | 100 | 92 | A+ | A- |
| Overall Grade: Age - Appropriate Design | | | B- | B- |
| | | | | |
| Fall Surfacing | 2000 % | 2004 % | 2000 Grade | 2004 Grade |
| Suitable materials provided | 68 | 83 | D+ | B- |
| Heights of equipment 8 feet or lower | NA | 98 | NA | A |
| Appropriate depth of loose fill | 44 | 4 | F | F |
| Six foot use zone had appropriate surface | 61 | 82 | D- | B- |
| Concrete footings were covered | 96 | 95 | A | A |
| Free of foreign objects | 92 | 92 | A- | A- |
| Overall Grade: Fall Surfacing | | | C | B |
| | | | | |
| Equipment Maintenance | 2000 % | 2004 % | 2000 Grade | 2004 Grade |
| Free of broken parts | 92 | 89 | A- | B+ |
| Free of missing parts | 85 | 98 | B | A |
| Free of protruding bolts | 95 | 94 | A | A |
| Free of noticeable gaps | 83 | 75 | B- | C |
| Free of head entrapments | 73 | 73 | C- | C- |
| Free of rust | 88 | 81 | B+ | B- |
| Free of splinter | 90 | 84 | A- | B |
| Free of cracks/holes | 100 | 100 | A+ | A+ |
| Overall Grade: Equipment Maintenance | | | B+ | B |

| Playground Equipment Profile* | | |
|---|-------------|-------------|
| Year of installation | 2004 | |
| Pre 1980 | 26% | |
| 1981-1990 | 14% | |
| 1991-1994 | 14% | |
| 1995-1997 | 2% | |
| 1998-present | 43% | |
| Not available | 11% | |
| | | |
| Kinds of Equipment** | 2000 | 2004 |
| Slides | 98% | 89% |
| Swings | 81% | 77% |
| Horizontal ladders | 24% | 17% |
| Sliding poles | 15% | 13% |
| Chinning bars | 5% | 6% |
| Seesaws | 24% | 23% |
| Merry-go-rounds | 19% | 9% |
| Geodesic domes | 5% | 4% |
| <p>* The number in these columns indicates the percentages of the year of installation. These may contain a combination of different installation years at each playground site. NA represents percentages that are not available.</p> <p>** The numbers in these columns reflect percentages of equipment pieces were found.</p> <p>Grading Scale: A=90-100 B=80-89 C=70-79 D=60-69 F=59></p> | | |

Georgia's Child Care Grade:

2000

B

2004

B



Comments

The National Program
For Playground Safety
America's
Playgrounds
Safety
Report Card
2004

The National Program for Playground Safety is housed at the University of Northern Iowa. For additional information about playground safety, contact the National Program for Playground Safety at the following address:

National Program for Playground Safety
School of Health, Physical Education, and Leisure Services
University of Northern Iowa
Cedar Falls, IA 50614-0618

800/554-PLAY (7529)
Fax: 319/273-7308
e-mail: playground-safety@uni.edu

World Wide Web:
<http://www.playgroundsafety.org>

*America's playgrounds
Make them safe*

**Georgia Child
Care**