

<b>Supervision</b>	<b>2000 %</b>	<b>2004 %</b>	<b>2000 Grade</b>	<b>2004 Grade</b>
Adults present	88	50	B+	F
Easily viewed	95	55	A	F
Crawl spaces	95	21	A	F
Supervision rules posted	0	0	F	F
<b>Overall Grade: Supervision</b>			<b>B+</b>	<b>F</b>
<b>Age-Appropriate Design</b>	<b>2000 %</b>	<b>2004 %</b>	<b>2000 Grade</b>	<b>2004 Grade</b>
Had separate areas	0	NA	F	NA
Signage for age group provided	0	NA	F	NA
Provided change of direction	100	82	A+	B-
Had guardrails	95	100	A	A+
Prevented climbing outside the structure	48	50	F	F
Supporting structure prevented climbing on	57	73	F	C-
<b>Overall Grade: Age - Appropriate Design</b>			<b>C-</b>	<b>C+</b>
<b>Fall Surfacing</b>	<b>2000 %</b>	<b>2004 %</b>	<b>2000 Grade</b>	<b>2004 Grade</b>
Suitable materials provided	86	95	B	A
Heights of equipment 8 feet or lower	NA	100	NA	A+
Appropriate depth of loose fill	25	57	F	F
Six foot use zone had appropriate surface	67	86	D+	B
Concrete footings were covered	95	96	A	A
Free of foreign objects	43	24	F	F
<b>Overall Grade: Fall Surfacing</b>			<b>C-</b>	<b>B-</b>
<b>Equipment Maintenance</b>	<b>2000 %</b>	<b>2004 %</b>	<b>2000 Grade</b>	<b>2004 Grade</b>
Free of broken parts	91	81	A-	B-
Free of missing parts	95	73	A	C-
Free of protruding bolts	75	91	C	A-
Free of noticeable gaps	48	59	F	F
Free of head entrapments	70	96	C-	A
Free of rust	62	46	D-	F
Free of splinter	70	17	C-	F
Free of cracks/holes	100	95	A+	A
<b>Overall Grade: Equipment Maintenance</b>			<b>C+</b>	<b>C</b>

<b>Playground Equipment Profile*</b>		
<b>Year of installation</b>	<b>2004</b>	
Pre 1980	32%	
1981-1990	10%	
1991-1994	27%	
1995-1997	18%	
1998-present	50%	
Not available	19%	
<b>Kinds of Equipment**</b>	<b>2000</b>	<b>2004</b>
Slides	44%	100%
Swings	52%	36%
Horizontal ladders	76%	81%
Sliding poles	76%	54%
Chinning bars	67%	54%
Seesaws	0%	0%
Merry-go-rounds	10%	0%
Geodesic domes	19%	18%

\* The number in these columns indicates the percentages of the year of installation. These may contain a combination of different installation years at each playground site. NA represents percentages that are not available.

\*\* The numbers in these columns reflect percentages of equipment pieces were found.

Grading Scale: A=90-100 B=80-89 C=70-79 D=60-69 F=59>

# Idaho's School Grade:


**2000**

**C**

**2004**

**C**

Comments



The National Program  
For Playground Safety  
America's  
Playgrounds  
Safety  
Report Card  
2004

The National Program for Playground Safety is housed at the University of Northern Iowa. For additional information about playground safety, contact the National Program for Playground Safety at the following address:

National Program for Playground Safety  
School of Health, Physical Education, and Leisure Services  
University of Northern Iowa  
Cedar Falls, IA 50614-0618

800/554-PLAY (7529)  
Fax: 319/273-7308  
e-mail: [playground-safety@uni.edu](mailto:playground-safety@uni.edu)

World Wide Web:  
<http://www.playgroundsafety.org>

*America's playgrounds  
Make them safe*

**Idaho  
School**