

<b>Supervision</b>	<b>2000 %</b>	<b>2004 %</b>	<b>2000 Grade</b>	<b>2004 Grade</b>
Adults present	50	67	F	D+
Easily viewed	96	84	A	B
Crawl spaces	100	86	A+	B
Supervision rules posted	4	0	F	F
<b>Overall Grade: Supervision</b>			<b>C+</b>	<b>C</b>
<b>Age-Appropriate Design</b>	<b>2000 %</b>	<b>2004 %</b>	<b>2000 Grade</b>	<b>2004 Grade</b>
Had separate areas	33	NA	F	NA
Signage for age group provided	0	NA	F	NA
Provided change of direction	94	100	A	A+
Had guardrails	75	100	C	A+
Prevented climbing outside the structure	96	90	A	A-
Supporting structure prevented climbing on	100	91	A+	A-
<b>Overall Grade: Age - Appropriate Design</b>			<b>C+</b>	<b>A</b>
<b>Fall Surfacing</b>	<b>2000 %</b>	<b>2004 %</b>	<b>2000 Grade</b>	<b>2004 Grade</b>
Suitable materials provided	87	95	B+	B+
Heights of equipment 8 feet or lower	NA	86	NA	B
Appropriate depth of loose fill	17	32	F	F
Six foot use zone had appropriate surface	49	90	F	A-
Concrete footings were covered	70	89	C-	B+
Free of foreign objects	87	91	B+	A-
<b>Overall Grade: Fall Surfacing</b>			<b>C-</b>	<b>B</b>
<b>Equipment Maintenance</b>	<b>2000 %</b>	<b>2004 %</b>	<b>2000 Grade</b>	<b>2004 Grade</b>
Free of broken parts	78	81	C+	B-
Free of missing parts	74	95	C	A
Free of protruding bolts	65	95	D	A
Free of noticeable gaps	74	95	C	A
Free of head entrapments	52	95	F	A
Free of rust	57	100	F	A+
Free of splinter	88	100	B+	A+
Free of cracks/holes	92	100	A-	A+
<b>Overall Grade: Equipment Maintenance</b>			<b>C</b>	<b>A</b>

<b>Playground Equipment Profile*</b>		
<b>Year of installation</b>	<b>2004</b>	
Pre 1980	0%	
1981-1990	0%	
1991-1994	15%	
1995-1997	45%	
1998-present	40%	
Not available	5%	
<b>Kinds of Equipment**</b>	<b>2000</b>	<b>2004</b>
Slides	70%	90%
Swings	52%	57%
Horizontal ladders	35%	90%
Sliding poles	39%	66%
Chinning bars	26%	26%
Seesaws	9%	0%
Merry-go-rounds	4%	10%
Geodesic domes	39%	30%
<p>* The number in these columns indicates the percentages of the year of installation. These may contain a combination of different installation years at each playground site. NA represents percentages that are not available.</p> <p>** The numbers in these columns reflect percentages of equipment pieces were found.</p> <p>Grading Scale: A=90-100 B=80-89 C=70-79 D=60-69 F=59&gt;</p>		

# Indiana's School Grade:


**2000**

**C**

**2004**

**B+**

Comments



The National Program  
For Playground Safety  
America's  
Playgrounds  
Safety  
Report Card  
2004

The National Program for Playground Safety is housed at the University of Northern Iowa. For additional information about playground safety, contact the National Program for Playground Safety at the following address:

National Program for Playground Safety  
School of Health, Physical Education, and Leisure Services  
University of Northern Iowa  
Cedar Falls, IA 50614-0618

800/554-PLAY (7529)

Fax: 319/273-7308

e-mail: [playground-safety@uni.edu](mailto:playground-safety@uni.edu)

World Wide Web:

<http://www.playgroundsafety.org>

*America's playgrounds  
Make them safe*

**Indiana School**