

<b>Supervision</b>	<b>2000 %</b>	<b>2004 %</b>	<b>2000 Grade</b>	<b>2004 Grade</b>
Adults present	75	0	C	F
Easily viewed	100	67	A+	D+
Crawl spaces	93	29	A-	F
Supervision rules posted	0	0	F	F
<b>Overall Grade: Supervision</b>			<b>B-</b>	<b>D-</b>
<b>Age-Appropriate Design</b>	<b>2000 %</b>	<b>2004 %</b>	<b>2000 Grade</b>	<b>2004 Grade</b>
Had separate areas	33	0	F	F
Signage for age group provided	25	0	F	F
Provided change of direction	100	90	A+	A-
Had guardrails	93	88	A-	B+
Prevented climbing outside the structure	57	18	F	F
Supporting structure prevented climbing on	86	15	B	F
<b>Overall Grade: Age - Appropriate Design</b>			<b>C</b>	<b>D+</b>
<b>Fall Surfacing</b>	<b>2000 %</b>	<b>2004 %</b>	<b>2000 Grade</b>	<b>2004 Grade</b>
Suitable materials provided	100	69	A+	D+
Heights of equipment 8 feet or lower	NA	100	NA	A+
Appropriate depth of loose fill	64	0	D	F
Six foot use zone had appropriate surface	100	46	A+	F
Concrete footings were covered	100	54	A+	F
Free of foreign objects	93	23	A-	F
<b>Overall Grade: Fall Surfacing</b>			<b>A-</b>	<b>D+</b>
<b>Equipment Maintenance</b>	<b>2000 %</b>	<b>2004 %</b>	<b>2000 Grade</b>	<b>2004 Grade</b>
Free of broken parts	79	31	C+	F
Free of missing parts	79	69	C+	D+
Free of protruding bolts	100	39	A+	F
Free of noticeable gaps	77	50	C+	F
Free of head entrapments	64	54	D	F
Free of rust	93	39	A-	F
Free of splinter	75	0	C	F
Free of cracks/holes	100	91	A+	A-
<b>Overall Grade: Equipment Maintenance</b>			<b>B-</b>	<b>D</b>

<b>Playground Equipment Profile*</b>		
<b>Year of installation</b>	<b>2004</b>	
Pre 1980	70%	
1981-1990	0%	
1991-1994	20%	
1995-1997	10%	
1998-present	40%	
Not available	23%	
<b>Kinds of Equipment**</b>	<b>2000</b>	<b>2004</b>
Slides	100%	92%
Swings	86%	100%
Horizontal ladders	86%	85%
Sliding poles	64%	54%
Chinning bars	38%	46%
Seesaws	8%	8%
Merry-go-rounds	14%	15%
Geodesic domes	14%	31%
<p>* The number in these columns indicates the percentages of the year of installation. These may contain a combination of different installation years at each playground site. NA represents percentages that are not available.</p> <p>** The numbers in these columns reflect percentages of equipment pieces were found.</p> <p>Grading Scale: A=90-100 B=80-89 C=70-79 D=60-69 F=59&gt;</p>		


# Wyoming's School Grade:

**2000**

**B-**

**2004**

**D**



Comments

---

The National Program  
For Playground Safety  
America's  
Playgrounds  
Safety  
Report Card  
2004

---

The National Program for Playground Safety is housed at the University of Northern Iowa. For additional information about playground safety, contact the National Program for Playground Safety at the following address:

National Program for Playground Safety  
School of Health, Physical Education, and Leisure Services  
University of Northern Iowa  
Cedar Falls, IA 50614-0618

800/554-PLAY (7529)  
Fax: 319/273-7308  
e-mail: [playground-safety@uni.edu](mailto:playground-safety@uni.edu)

World Wide Web:  
<http://www.playgroundsafety.org>

*America's playgrounds  
Make them safe*

**Wyoming  
School**